

# Haul Road Crossing

This haul road is the main supply and output route for the mine, used by class 787 trucks.

During the 2011 wet season flooding washed out the Middlemount Coal's main haul road at the Roper Creek crossing. Hawkins Group were engaged to undertake the major repairs, including installing culverts and concrete head walls. All aspects of safety management were implemented during construction to allow heavy vehicle interface with the construction team The project was completed without any loss of production time for the mine and to a tight schedule before the next wet season.







#### Client:

Middlemount Coal

#### Location:

Middlemount, Central Queensland

### Project value:

\$1.8 million

#### Contract type:

Construct only

– lump sum

## Completed:

2012

General construction

Mining/resources

1011

Remote

1